


VALBRUNA

SLATER STAINLESS, INC.

2400 Taylor Street West, P.O. Box 630 Fort Wayne, Indiana USA 46801 Phone: 260-434-2892 Fax: 260-434-2605



Product Certification Report

Report Number: 4421680

			260-434-289			905	Ce	rtif	he i	Or	Tan 1	2	2009	Page	7	~ F	1
Order I.D. Order Date			ate	Certified on Jan 13, 2009							2003	rage		of			
0900050 015 1/08/09			3/09	316D3.ORT								F18821					
10000000	Dim 1 Dim 2		Din	n 3	Hea	t I.D.	Custome	omer I.D. Customer Purchase Order					100				
	0000	.0000		0000 247874 002476 901002115													
Product Shape Product Surface													Customer G	rade		_	
	Rounds HR & Rough Turne								eđ					316/316L			
Length (In							Bill of	Lading #	Welg	ght							-
1	132.000 Min. 156.000 Max. 409397																
Ship To VALBRUNA CANADA LTD. 8724 HOLGATE CRESCENT MILTON, ONTARIO L9T5Z1									Soc	ld	VALBRUM 8724 HO MILTON,	DLG.	ATE CR	ESCENT			

							<u>.</u>					
Lifts: 0	015 0	016 001	7									
NACE MR017				ASTMA	276-08			Δ S.TTN	1A 479	-060		
ASMESA 479					-, 0 00			ADII	IA 4/5	00a		
CHEMICAL	ANAL	YSIS										
C	Mn	P	S	Si	Cr	Ni	Mo	Cu	Co	N		
.016	1.54	.029	.030	. 60	16.88	10.09	2.02	.70	. 09	. 07		
HB										.07		
180												
TENSILE	77.50 PM											
TS (PS		.2%YS (PS	I) %	EL(2")	%RA							
881		460		51.8	74.0							
MACRO AS		40/E381										
MACRO												
OK	<u>-</u>											
OK												
GRAIN SI		TM E112										
GRAIN	SIZE											
A CITIM A D	C2 PP	30 5/2										
ASTM A 2		AC E(A	Utili	zed)								
OKALIC												
		in and ma		11.(1								
Heated to 19 Chemical tes	eting ne	in, and war	ter quer	iched (he	eating tim	e & temp	appropria	te for o	ptimun	quality)).	
Contained to	sung pr	arounica (c) One or	Several	or the tol	lowing A	STM meth	nods: E	415, E5	72, E10	19, E10	85, E1086.
	O. 1011	THURST AL	IOV CONT	I ALLII I ALLI	311 13/13/14	ald rangir						120
Material me	forma	taly, mani	nacture	a in the	United St	ates.						
Material con	TOTILS	to fisted sp	ecificat	ions.								

Results relate only to the items tested. Certification shall not be reproduced except in full, without written approval of Valbruna Stainless Inc. The recording of false fictitious, or fraudulent statements on this document may be punished as a felony under federal statutes, including Federal law, Title 18, Chapter 47. Consult material safety data sheet (MSDS) for hazard info. I hereby certify that the reported figures are correct as contained in the records of the corporation.

Quality system is compliant with ISO 9001:2000. Produced in accordance with EN 10204 3.1B.

Manager Laboratory Services

